NPS Form 10-800 VLR-8/15/89 NRHP- 12/19/90
(Rev. 8-88)

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

1917

OMB No. 1004-0016

OCT 03 1930

NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

, om to too y type an emilian			
1. Name of Property			
historic name BFLLEVUE			
other names/site number (DHR 09-0	13)		
Dill	231		
2. Location			
street & number VA ROUTE 64	13	N.	not for publication
city, town GOODE	+3		vicinity
	VA county BEDFORD		15 zip code 2455
SIGIO VIRI-INIA COGO	A COUNTY BEDFORD	0000	15 210 0000 24550
3. Classification			
	Category of Property	Number of Becour	ces within Property
	- · · · · ·		, ,
private	building(a)	Contributing	Noncontributing
public-local	district	4	0buildings
public-State	site		O sites
public-Federal	structure	<u> </u>	structures
Ĺ	object		Oobjects
		_7	O Total
Name of related multiple property listing:		Number of contribu	iting resources previously
N/A		listed in the Nation	al Register
0. 4 (5. 1 . 1 4			
I. State/Federal Agency Certification	20		
Signature of certifying official VA DEPARTMENT State or Federal agency and pureau In my opinion, the property meets Signature of commenting or other official	OF HISTORIC RESOURCES does not meet the National Regi	ster criteria. See co	ntinuation sheet.
State or Federal agency and bureau			(((()))
. National Park Service Certificatio	n:		-41-111 €. i.i.
hereby, certify that this property is:			
entered in the National Register.		7 3.75	្ត
See continuation sheet.			
determined eligible for the National			
	er i til grift og fler skriver i det skriver		and the property of the control of t
Register. See continuation sheet.			
determined not eligible for the	200 1200 350 500 500	សាមាធិ មាន ស្រាស់នៅ	្រាស់ ស្រាស់ ម៉ាស់ ម៉ូនិស្ស ខ
National Register.			
removed from the National Register.			
other, (explain:)	_		
	Signature of the	- M	Date of Action

6. Function or Use	
Historic Functions (enter categories from instructions) DOMESTIC: SINGLE DWELLING	Current Functions (enter categories from instruction DOMESTIC: SINGLE DWELLING
DOMESTIC: SECONDARY STRUCTURE	DOMESTIC: SECONDARY STRUCTURE
ANDSCAPE: GARDEN	LANDSCAPE: GARDEN
UNERARY: CEMETERY	FUNERARY: CEMETERY
7. Description	
Architectural Classification enter categories from instructions)	Materials (enter categories from instructions)
FARLY REPURE TO THE TOTAL	foundation BRICK
EARLY REPUBLIC: FEDERAL	walls BR ICK
	roof METAL
	other

Describe present and historic physical appearance.

SUMMARY DESCRIPTION

Located off of Route 221 east of Bedford, Bellevue is a two-story brick residence constructed in three phases during the nineteenth century, beginning about 1824 and concluding around 1870. The portion first built was Federal in style and likely had a side-hall plan with a hall and two rooms on each floor. An addition was constructed around 1840 that virtually doubled the size of the house and resulted in a symmetrical rectangular structure with a central hall plan. This addition, which also had two rooms and a hall on each floor, is Greek Revival in its detailing. The front elevation reveals evidence of these two phases in the brickwork by the slightly irregular placement of windows and different window detailing. Sometime between 1866 and 1870, two frame wings were added to either end. The location of a successful school during the late nineteenth century, the property still retains a dormitory building known as Inkstand, as well as three dependencies, a garden, and a family cemetery, all of which contribute to the significance of Bellevue.

ARCHITECTURAL ANALYSIS

Bellevue is located in a rural setting eight miles east of Bedford in the vicinity of Goode. It is surrounded by farm fields and wooded areas, and affords beautiful views of the Peaks of Otter. An unpaved drive leads from the public road and terminates at the southern end of the house, which is surrounded by a large lawn with cedars and magnolias. Brickwalks circle the house, and a garden and cemetery are located to the north.

Though built in two phases, the overall appearance of the house is uniform, with symmetrical elevations covered by a low-pitched, standing-seam-metal hipped roof and flanking end wings. The dentilled cornice with its band of vestigial modillions is consistent on both sections. Windows, while regularly placed and consistently six-over-six double-hung, differ in the treatment of the openings. The openings of the earlier section have brick jack arches and molded sills, whereas the 1840 addition has wooden lintels detailed with paterae corner blocks and plain sills. There is slightly more space between the center bay and the north section than between the center and the south addition. The entire brick

The second secon

we there is a second of the se

X See	continuation	shoot
-------	--------------	-------